

SOUTHERN MAINE INDUSTRIES ROHS COMPLIANT PROCESSES

**Anodize- clear, black, gold, green, red, blue, bronze,
gray and purple.**

Hardcoat- all colors above

Zinc- clear(blue) only

Copper

Tin

Silver

Black Oxide

Black Passivate

Passivate

Bright Dip (copper and brass)

Powder Coating